	Carleton University Joint Health and Safety Committee - Workplace Inspection Report			
Building:	Health Sciences	Inspected	James LaFortune, Allison Jaworski and Nancy Delcellier	
Area Inspected:	Labs and Vivarium	Tel:		
Date:	May 7, 2021	Email:		

				Area Supervisor or Designated Con	ntact to Com	plete
Department	Room	Hazard	Recommended Corrective Action	Corrective Action Taken or Planned	Date	Initial
	Building entrances	No hand sanitizers upon building entry	Install hand sanitizing stations at the entrances of the Health Sciences Building			
	All lab spaces	Fire extinguishers are only housed outside of the lab spaces	Confirm needs with CSS Fire prevention Officer			
Health Sciences and Neuroscience			Remove chair with cloth cushion. All materials in a CL2 lab must be cleanable		May 19	MRH, MH

Health Sciences and Neuroscience			All chemicals are now in the inventory		MRH, MH
Health Sciences and Neuroscience	2201J (corridor outside of 2201E)	9 in W	Has been raised with FMP-PDC. Working on a resolution	May 14	AFJ

Health Sciences and Neuroscience	2201E		Remove ice buckets so there is a minimum of 6in clearance below the ceiling	Items have been removed	May 19	MRH, MH
Health Sciences and Neuroscience	2201E	Glassware on top of fridge	Remove glassware from the top of fridge	Glassware has been removed	May 19	MRH, MH

Health Sciences and Neuroscience	2201E	Missing WHMIS sticker on HCI container in fume hood	Add a WHMIS sticker	WHMIS sticker has been added	May 19	MRH, MH
Health Sciences and Neuroscience	2201E	"No Food" sign missing from microwave	Add "No Food" sign to microwave	Sign has been added	May 19	MRH, MH

		Eye wash installed in such a manner that there is no appropriate drain for the run-off water		Has been raised with FMP-PDC. Working on a resolution	May 14	AFJ
		Table is obstructing clear path of egress				
Health Sciences and Neuroscience	2308		Move the table out of the path of egress	Done	May 19	МН

Health Sciences	3201A	Equipment packaging stored in a CL2 lab space	Remove all packing materials from a CL2 lab space. All materials in a CL2 lab space must be easily cleaned.	Packing materials have been removed	МН
Health Sciences	3201A	Door taped open	Tape removed by inspectors. Occupants need to be informed not to obstruct door locks	All users have been informed again not to tape the locks.	МН

Health Sciences	3201B	Biohazard container from external company found.	Carleton no longer has a contract with this external company and all remaining containers were to be returned. Please contact Tina Preseau for steps to return this container so the University is not charged for it.	We arranged for the container to be removed	МН
Health Sciences	3201B	What was poured down the sink?	Sink will need to be cleaned and assessed if any damage was done.	Sink was cleaned. There doesn't appear to be any damage.	МН

Health Sciences	3201B	NOTE: No communal lab coats for teaching labs this year		Lab coats were removed	МН
Health Sciences	3201C	Door taped open		All users have been informed not to tape the locks.	МН
Health Sciences	3201C	Equipment packaging stored in a CL2 lab space	Remove all packing materials from a CL2 lab space. All materials in a CL2 lab space must be easily cleaned.	Packing material from recently delivered equipment has been removed from 3201C.	МН
Health Sciences	North end of 3201	Food container found on lab sink	Remove. Food containers are not permitted in lab spaces	Food container was removed.	мн

Health Sciences	North end of 3201	Eye wash obstructed from items stored in front of it	Remove items obstructing the eye wash station.	Clutter was cleaned up and the eyewash station is accessible.	МН
Health Sciences	3201D	No sign indicating that this is a CL2 microbiology lab	Post sign	This seems to be a building deficiency issue that should have been identified at building inspection since this room is a designated microbiology room. We can put up a printed sign but proper sign should come from EHS/FMP?	МН
Health Sciences	3201D	Lots of cardboard stored in CL2 lab	Remove cardboard from CL2 lab	Boxes were removed from the lab.	МН

Health Sciences	North end of 3201	Two fume hoods closest to microbiology room: Missing waste labels on waste containers	A proper label was attached to the container.	МН
Health Sciences	North end of 3201	Box of N95 masks found on counter top. Question: Has the individual that wear these been fit tested for N95 masks?	Masks were removed from the lab.	MH

Health Sciences	North end of 3201	Ensure that all chemicals are recorded in Carleton's Chemical Inventory	We are in the process of adding these chemicals to the CCI.	M	ИΗ
Health Sciences	North end of 3201	Move Perchloric acid to store at a height where there is little likely hood it will fall	It was moved down.	N	ИΗ

Health Sciences	North end of 3201	Chemical station: Missing "No Food" label on microwave		No Food label was put on the microwave.	МН
Health Sciences	Corridor in front of 3201L		Gas cylinders are not to be stored for extended periods on carts. Move to the gas cylinder storage rooms for proper storage	We do not have a tank cage in HSB. This tank was empty and was in the process of being transported to Stores for storage before pickup. However, given our limited access to Stores due to COVID-19 restrictions, access to the building was in the process of being organized. This will not happen again.	MH

Health Sciences	3201L	MARKET		Has been raised with FMP-PDC. Working on a resolution	May 14	AFJ
Health Sciences	3201L	No instructional signage for proper operation of the "push to" EXIT buttons to properly operate the doors while the mag locks are engaged	Install instructional signage	WO has been created in eShop	May 14	ND

Health Sciences	3201M		overflowing the container	This space is not regularly being used and the waste was missed during routine collections. This waste has been autoclaved and it will not happen again.		МН
Health Sciences	3201M		Romovo wood storago dividors from	Wood partitions have been removed and replaced with plastic containers.		МН
Health Sciences	3201M	No instructional signage for proper operation of the "push to" EXIT buttons to properly operate the doors while the mag locks are engaged	Install instructional signage	WO has been created in eSHop	May 14	ND

Health Sciences	South end of 3201	No label on Nalgene jug	Add label to jug detailing contents of container	A label has been added to the jug identifying the content as distilled water.	МН
Health Sciences	South end of 3201	Good job collecting chemical inventory labels!			

Health Sciences	South end of 3201	antainers detailing their contents	A label has been added to the spray bottle identifying the contents as 70% ethanol.	МН
Health Sciences	South end of 3201	 Ensure that all chemicals are recorded in Carleton's Chemical Inventory	We are in the process of adding these chemicals to the CCI.	МН

T	1	Overflowing higherend wests has	T		<u> </u>
Health Sciences	South end of 3201		Ensure that biohazard waste containers are changed regularly to prevent biohazardous waste from overflowing the container	Biohazard waste was removed.	МН
Health Sciences	South end of 3201	On the south most end of the open lab, none of the students wore lab coats	all necessary lab PPE at all times in	Lab personnel always wear lab coats and all required PPE while working in the labs. The persons identified during the inspection were contractors working to resolve an issue on a piece of equipment.	МН
Health Sciences	3201H	Electric strike on door damaged from doors being taped open	electric strike needs to be repaired/replaced ASAP and occupants need to be informed not	The users were informed not to tape the lock. The lock is functioning properly. CA WO Created for inspection.JB	МН

Health Sciences	3107	Rearrange boxes so they are not stacked so high and ensure that a step ladder is available so occupants can safely reach items stored in this space	Boxes were rearranged into a single row.		МН
Neuroscience	5001 (North Corridor)		Phone receiver was broken and has been replaced	May 19	AFJ
Neuroscience	Lab entrance	Young children are not permitted in lab spaces. This faculty member has already been told this once before.	Chair has reminded faculty about children not being permitted in the lab spaces	May 19	MRH

Neuroscience	5103	Gas cylinders are not supposed to be stored with regulators on them. Disengage the regulators and cap the gas cylinders			
Neuroscience	5201A	Tape removed by inspectors. Occupants need to be informed not to obstruct door locks especially on CL2 lab spaces	RESOLVED	May 19	MRH

Neuroscience	5201A	Gas cylinder without storage cap on	Gas cylinders need to be properly stored. Add cap to idle gas cylinders		May 19	MRH
Neuroscience	5201B	Hearing protection available for sonicator?		YES AVAILABLE IN A UNDISCLOSED LOCATION	May 19	MRH
Neuroscience	5201C	ino label off spray bottles		TERESA CELL CULTURE: RESOLVED; labels added	May 19	MRH
Neuroscience	5201C	Consider moving camera lens off the edge of the shelf. It may fall and damage your camera		TISSUE CULTURE TERESA: RESOLVED; equipment moved	May 19	MRH

Neuroscience			Install missing card swipe, or at least cover the hole	Has been raised with FMP-PDC. Working on a resolution CA WO created to install blank cover plate.	May 14	AFJ
--------------	--	--	--	--	--------	-----

Neuroscience	5201	Glassware and boxes stored too high on shelfs that do not have ridges to prevent the items from slipping off the edges	Remove glassware and boxes that are stored too high	RESOLVED – MOVED PLASTIC UP AND GLASS DOWN	May 19	MRH
--------------	------	--	---	---	--------	-----

	5201		Add signs	Signs added	May 26	MRH
el	ne hood North and of 5201	Too many items stored within fume hood for proper operations	Clean/clear out fume hood	CLEANED OUT WASTE	May 19	MRH

Neuroscience	5201	Lab coats thrown in a large pile		NEED TO FIND A CLEANING SERVICE; checking in on cleaning service	May 19	MRH
Neuroscience	South end of 5201	Lab sink closest to 5201Q: sink so overcrowded that the eye wash station is obstructed	ctation is freely acceptable	STYROFOAM REMOVED Will carry out a general Styrofoam clean out	May 26	MRH

Neuroscience	5201		Ensure that all chemicals are recorded in Carleton's Chemical Inventory	ARGEL TO WORK WITH TINA	May 26	MRH
--------------	------	--	---	-------------------------	--------	-----

Neuroscience	South end of 5201	Fume hood closest to Q: Waste labels are illegible	Add waste labels that clearly indicate the hazards	these bottles are under the fume hood we use, but they are not waste bottles. They are the reagents we use for staining and are labeled with the name of the reagent - it's legible in person but not from the photo. We store the reagents in bottles rather than leaving them in staining jars inside the fume hood. It cuts down on fume hood clutter and the reagents last longer.	My 26	MRH
--------------	-------------------	--	--	--	-------	-----

Neuroscience	South end of 5201	Fume hood labeled "Hildebrand": Waste labels missing	Add waste labels	Labels added	May 28	MRH
Neuroscience	South end of 5201	Fume hood labeled "Hildebrand": Fume hood is overcrowded	Clean/clear out fume hood	Excess materials cleared out	May 28	MRH

Neuroscience	South end of 5201	Fume hood labeled "Abizaid": Waste labels missing		Waste labels added	May 28	MRH
Neuroscience	South end of 5201	Corner next to fume hood labeled "Abizaid": Bottle of xylene found on the floor	Xylene move by inspectors to flammables cabinet. Xylene cannot be stored on the floor	RESOLVED ABIZAID	May 26	MRH
Neuroscience	South end of 5201		Remove wood lab coat hanger. Wood is not a permissible material in CL2 facilities	NEED LAB COAT WASHING SERVICE RYAN Wood rack has been removed	May 26	MRH
Neuroscience	South end of 5201		all necessary lab PPE at all times in	REMIND PIS Send out a general email to remind personnel to wear coats	May 26	MRH

Missing official laser signage 5201M Neuroscience 5201M Install official laser signage	
---	--

Neuroscience 520°	Chemicals (isoflurane and flammables) stored in an unrated cabinet		Chemicals have been moved	May 26	MRH
-------------------	--	--	---------------------------	--------	-----

Neuroscience	Doors to	No instructional signage for proper operation of the "push to" EXIT buttons to properly operate the doors while the mag locks are engaged	Install instructional signage	Wo created in eShop	
Neuroscience		Lab signage required 6202 Research Lab TPOLITICAL IT SCIENCE ANA MASK.	The larger signage format is required for lab spaces. Install correct signage		

	CC	Chemicals missing chemical inventory bar codes	Ensure that all chemicals are			
Neuroscience	6202		recorded in Carleton's Chemical Inventory	Worked with Tina	May 26	MRH
Neuroscience	6202	Missing "No Food" sign on microwaves	Add sign	Sign added	May 26	MRH

Neuroscience	6202		Remove cardboard waste from lab space	Waste has been removed Send out general email to all PIs to remove unused boxes and styrofoam	May 26	MRH
Neuroscience	6202	Missing labels on spray bottles and Nalgene jugs	Add labels to all spray bottles and containers detailing their contents	Labels added	May 26	MRH

Neuroscience	6202	Flammable solvent stored on countertop	Store flammable solvents in flammable cabinets	Solvents moved and stored properly	May 26	MRH
Neuroscience	6202	Table stored in path of egress		Table has been moved	May 26	MRH
Neuroscience	6202	None of the students wore lab coats	Ensure that all lab personnel wear all necessary lab PPE at all times in the lab	Remind PIS and personnel	May 26	MRH

Neuroscience	6202A		Tubing (tripping hazard) was	Tubing has been moved permanently	May 26	MRH
--------------	-------	--	------------------------------	-----------------------------------	--------	-----

Neuroscience	6202A	Inappropriate gas cylinder brackets (2)	Properly secured gas cylinder brackets will need to be installed or gas cylinders stored in the gas cylinder storage room	Bracket has been fixed and secured properly	May 26	MRH
--------------	-------	---	---	---	--------	-----

Neuroscience	6202A	Water bottle found in lab space	Cannot eat or drink in a lab space. All food and drink must be removed from the lab space ASAP	PIs and personnel reminded	May 26	MRH
Neuroscience	6202A	Items stored on and up against gas manifold set-up	Clear debris off the manifold set up	Debris removed	May 26	MRH

			<u></u>			
Neuroscience	6202A	Missing secondary container	Place in secondary container	Secondary container added	May 26	MRH
Neuroscience	6202B	Items stored on against gas manifold set-up	Clear debris off the manifold set up	Debris removed	May 26	MRH

		1			Т	
Neuroscience	6202B		Reinstall the holder so it is two thirds of the cylinder's height high			
Neuroscience	6202A		Inventory	Worked with Tina and inventory entered	May 26	MRH
ACVS	6205H	EHS verification stickers on downdraft tables missing	Contact EHS to install EHS verification stickers	I will email EHS about it (Sarah Dunlop)		

ACVS	6206		Removing items obstructing clear path to the electrical panels	I will clear that space on May 18, 2021 (Sarah Dunlop)	
ACVS	7301	Missing sign indicating not to use the eye wash station in front of clean side cage wash until the hot water issue is resolved	Install sign	I will place a sign on the eye wash station (Sarah Dunlop)	

ACVS	7307A	Ladder in front of staircase to mechanical room	Remove ladder	Removed	
ACVS	Emergence exit to staircase B		Fix emergency exit door so people can exit L7 from it	FMP was contacted May 7, 2021 and was fixed same day	AFJ

REPORT DISTRIBUTION (within two working days following workplace inspection)

Area Supervisor(s), Designated Contact(s), Building Authority:	Chuck Macdonald	Shall provide a written response outlining corrective action taken or planned within 21 calendar days. Send responses to nancy_delcellier@carleton.ca , as well as to worker member identified above
JHSC Management Member Contact:	Allison Jaworski	To ensure appropriate report distribution.
Environmental Health and Safety:	Nancy Delcellier	For tracking response from Area Supervisor(s).
JHSC Worker Member:	Linda Cruz	For tracking completion of JHSC workplace inspections.